

HOME INSPECTION REPORT



594 Indian Grove

Toronto

Prepared for: Kevin Alvarez

Prepared by: Bob Papadopoulos P.Eng., RHI *

Inspection Date: Aug 25 2020



www.redbrickinspections.ca
bob@redbrickinspections.ca
416-829-6655

Please Read: http://redbrickinspections.ca/docs/1_Introduction_Reference_Guide.pdf

*please see credentials at end of report

SIGNIFICANT ITEMS

*This page should not be considered as the complete report.
Please read all other forms contained within the Home
Inspection Report*

*For the purposes of this report,
the front of the house is considered
to be facing: East*

ROOFING The roof surfaces through-out are overall in good repair.

EXTERIOR Overall well maintained.

STRUCTURE Budget for repairs/improvements in the crawl spaces - see details

ELECTRICAL The 100 AMP service size is adequate and the wiring has been upgraded to copper grounded.

HEATING 20-yr-old high-efficiency forced-air gas furnace with a typical life expectancy of 20-25-yrs.

COOLING/
HEAT PUMPS 14-yr-old air-conditioner with a typical life expectancy of 15-20-yrs.

INSULATION/
VENTILATION Restricted access to roof and wall spaces therefore insulation not determined.
Crawlspace improvements recommended.

PLUMBING The water main has been upgraded to copper and the supply piping in the house is copper and plastic with good water pressure overall. Some upgrades to main waste drains. The washrooms and kitchens are in good repair.

INTERIOR Overall well maintained.

OVERALL RATING

The following rating reflects both the original quality of construction and the *overall* current condition of the home, based on a comparison to *similar* homes.

Below Typical

Typical

Above Typical

Prior to reviewing the Home Inspection Report please read the Terms and Conditions of the Home Inspection and the Standards of Practice of the Ontario Association of Home and Property Inspectors available online at www.redbrickinspections.ca <http://redbrickinspections.ca/wp-content/uploads/2015/06/StandardsofPractice-OAHI-Rev.pdf>

Description				
Roofing Material:	Location:	Leakage Probability:	Chimney(s) Type:	Location:
Asphalt Shingles:	Slope:	Low	Brick Abandoned:	South
Modified Bitumen:	Flat:	Low		

Limitations		
Roof Inspected By:	Access Limited By:	Chimney Access Limited By:
Binoculars Walking On From Edge		

Observations/Recommendations

Sloped Surface: [overall surface in good repair](#)
 Flat Surface: [overall surface in good repair](#)



Skylight(s): [overall in good repair](#)



Description

Gutters & Downspouts: Aluminum:	Downspout(s) Discharge: Various Above Grade	Lot Topography: Flat	Walls & Wall Structures: Brick Vinyl Siding Wood siding
------------------------------------	--	-------------------------	--

Limitations

Exterior Inspection from Ground Level

Observations/Recommendations

WALL SURFACES:

Brick: overall in good repair, monitor for mortar repairs as required

Vinyl Siding: overall in good repair

Wood siding: requires general repairs and maintenance



PORCH overall in good repair

Note: Maintain Gutters & Downspouts annually. Extend Downspouts at least 6-feet away from the house

** Any or all these items may contribute to **Basement Leakage**. Please see Interior Form

Description

Configuration:	Foundations:	Floor :	Walls :	Roof/Ceiling Framing:
Basement:	Brick Masonry Block	Wood Joists	Wood Frame (Siding) Wood Frame(Brick Veneer)	No Access
Crawl Space:	Brick Not Visible			

Limitations

Restricted Access to:	Foundation Wall Not Visible: <u>90</u> %
Wall Space	Crawlspace Inspected From Access Hatch :limited view of perimeter
Roof Space	see below
Roof Space	

Observations/Recommendations

FLOORS: west crawlspace: wood framing is at or below grade which can lead to rot, although this is an older condition recommend budgeting to excavate around exterior perimeter for further evaluation and repair of framing, also install concrete sill with damp-proofing, it was noted that concrete has been installed around south portion to minimize wood soil contact



Wood Column: west crawlspace: floor has been 'shored up' though overall low quality, monitor performance - budget to replace as above

FLOORS: east crawlspace: framing is above grade, overall in good repair as observed from crawlspace

FOUNDATIONS: east crawlspace: typical mortar deterioration, older condition, budget for repairs



Stair Opening: basement: shored up - typical, 2nd level- typical sagging

Description

Service Size: 100 AMP (240volts)	Service Entrance Cable:	Distribution Wire:
Main Disconnect/Service Box	Location: Overhead	Copper
Rating: 100 AMP	Type of material: Not Visible	Grounded
Description: Breakers		
Location: Basement		
Distribution Panel	System Grounding:	
Rating: 100 AMP	Description: Copper	
Description: Breakers	Location: Water Pipe	Ground Fault Circuit Interrupter:
Location: Basement		Location: Outside Kitchen Bathroom(s)
Auxiliary Panel(s):	Outlets	
Rating: AMP	Description: Grounded	
Description:	Number of Outlets:	Arc Fault Circuit Interrupter:
Location:		Location:

Limitations

Main Disconnect Cover Not Removed

Observations/Recommendations

SERVICE PANEL: overall in good repair



BRANCH WIRING: based on random sampling it was determined the wiring has been upgraded throughout

Note 1: All recommendations are safety issues - Treat them as high priority.

Note 2: Please ensure accurate labelling on panels.

REFERENCE LINK

http://redbrickinspections.ca/docs/6_Heating_Reference_Guide.pdf

594 Indian Grove

HEATING



Aug 25 2020

page 6

Description

Description:	Efficiency:	Rated Input:	Approx. Age:	Life Expectancy:	Fuel:	Shut Off at:
Hot Water Boiler:	High	75 x1000BTU/hr	20 yrs.	20+ yrs.	Gas	Meter-Exterior
Electric Heater(s):						

Exhaust Vent Arrangement: [Plastic Through-Wall Vent](#)

Limitations

Heat Loss Calculations Not Done	A/C Presently Operating
Heat Exchanger- Inaccessible	

Ref#*

Observations/Recommendations

FORCED AIR FURNACE: [continue servicing until replacement becomes necessary](#)



REFERENCE LINK

http://redbrickinspections.ca/docs/7_AC_Heat_Pump_Reference_Guide.pdf

594 Indian Grove

COOLING/Heat Pumps



Aug 25 2020

page 7

Description

Description:	Cooling Capacity:	Approx. Age:	Typical Life Expectancy:
Air Conditioner (air-cooled):	24 x1,000 BTU/hr	14 yrs. old	15 to 20 yrs.

Limitations

Cooling Performance

Supply Temp F:	55
Return Temp F:	70

Ref#*

Observations/Recommendations

AIR CONDITIONER: **aging unit, continue servicing until replacement becomes necessary**





Description

Material:	Location	R-Value	Air/Vapour Barrier:	Venting:
Mineral Wool:	Crawl Space Floor:	12	Not Visible	Roof Soffit

Limitations

Access Not Gained To Wall Space	Access Not Gained To Roof Space
Access Not Gained To Flat Roof	Crawlspace Viewed From Access Hatch

Ref#*

Observations/Recommendations

Crawlspace Floor: [remove debris, install moisture barrier over soil](#)

WALLS: [consider installing spray foam insulation around perimeter to reduce heat loss](#)

FLOORS: [crawlspace: some areas of main level floor have been insulated](#)

Pipes: Unheated Areas: [crawlspace: insulate supply pipes to minimize risk of freezing and/or install heating cable to pipes](#)





Description

Service Piping into House: Copper	Main Shut Off Valve at: Basement	Water Flow (Pressure): Good
Supply Piping & Pump(s): Copper Plastic	Waste Piping & Pump(s): Plastic Cast Iron	Water Heater Type: Induced Draft Fuel Type: Gas Capacity: 40 Gal Age Yrs.: 1 Life Expectancy: 15

Limitations

Isolating/Relief Valves & Main Shut Off Valves Not Tested	Concealed Plumbing not Inspected
Kitchen and Laundry Appliances Were Not Inspected	Tub/Sink Overflows Not Tested

Ref#*

Observations/Recommendations

WATERMAIN: upgraded to copper

SUPPLY PIPING:

Galvanized Steel: some in basement: replace and install faucet on exterior wall

WASTE PIPING:

Basement Floor Drain: none: budget to install with sump pump

Washroom(s): overall in good repair

Kitchen(s) overall in good repair

Description				
Floor Finishes: Wood Ceramic Tile Laminate	Wall Finishes: Plaster/Drywall	Ceiling Finishes: Plaster/Drywall	Windows: Single/Double Hung Casement Double Glazing	Exterior Doors: Metal
Fireplaces:	Fireplace Fuel:			

Limitations	
Restricted/No Access To: _____ CO Detectors, Security Systems, Central Vacuum, Chimney Flues Not Inspected Storage/Furnishings in Some Areas Limited Inspection	Foundation Not Visible <u>90</u> % Drainage Tile Not Visible

Ref#*	Observations/Recommendations
-------	------------------------------

Floors/Walls/Ceilings: overall in good repair
Trim/Cabinets/Counters: overall in good repair

Windows/Doors: upgraded double glazed units

**Crawlspace Leakage: typical efflorescence, staining and dampness for older foundation
see steps below

**Basement Leakage: it appears the basement has been damp-proofed which will minimize moisture



CO/Smoke detectors: please ensure one per level each with annual maintenance, this is a life safety concern and mandatory by law

** Steps recommended in order to minimize basement leakage

1. gutters, downspouts, grading, driveways: ongoing maintenance and repair/see Exterior
2. cracks/form ties on foundation: monitor/repair as required
3. excavation/damp-proofing: monitor basement, consider step 3 as a last resort

Environmental/Health Concerns: http://redbrickinspections.ca/docs/11_Environmental_Reference_Guide.pdf



Bob Papadopoulos P.Eng, RHI

- **Over 20 years of building inspecting experience in Toronto and the GTA**
- **Over 6,000 residential and commercial buildings inspected**

Bob has inspected over 6,000 residential and commercial buildings of various descriptions and reporting on conditions of major systems including structure, building envelope and mechanical systems, specific problem investigations and pre-renovation inspections. In the past Bob has helped train Home Inspectors and assisted in the creation of educational courses on home inspecting as well as taught Home Inspection courses at Seneca College. Bob also has experience in the construction industry inspecting many large scale projects through-out the GTA. He also served in the Canadian Navy as a Marine Mechanic and Ships Team Diver.

Professional Designations

- P.Eng. (Professional Engineer of Ontario) <http://www.peo.on.ca/>
 - RHI Registered Home Inspector <http://www.oahi.com/>
 - Environmental Site Assessment: ESA Phase 1 Certified <http://aesac.ca/>
-